



TANNERY MACHINES AND SPARE PARTS



Splitting machines

The most required spare parts for this kind of machine are:

- splitting bandknives
- section roller
- gauge roller
- rubber roller
- scrapers
- grinding wheels
- all spare parts

We can also supply all "MERCIER" spare parts